Master Maintenance Project Rotation List
CoastalBend College
Updated 12/11/18

		Estimated Construction Cost		Estimated Construction Materials Testing Fees 1.5% of Est. Construction cost		Estimated Project Contingency 15% of Construction Cost	Estimated Escalation for project 10% of Construction Cost	Project Totals	Priority Comments
	BUILDING ENVELOPE								
asb	Floor Tile Repair/Replace	\$	100,000.00	\$	1,500.00	\$ 15,000.00	\$ 10,000.00	\$ 126,500.00	Floor tile is cracking in major traffic areas (hallways only phase 1). 20,000 sq.ft. @ \$5 p/sq.ft. (Alice & PL) Classrooms estimated at same pricing p/sq.ft. for phase 2
	Roof Replacement	\$	176,000.00	\$	2,640.00	\$ 26,400.00	\$ 17,600.00	\$ 205,040.00	Roof at KV Site is deteriorating and leaking in sections. Replace with exact roof is listed. Replace with higher pitch "Galvalume" panelling - \$465,000 (financing available).
	Upgrade lighting and controls, occupancy sensors, college-wide	\$	150,000.00	\$	-	\$ 22,500.00	\$ 15,000.00	\$ 187,500.00	Convert to LED lighting. EPA compliance regulation is reduced with removal of flourescent bulbs and bulb life expands from 8,000 hours to 25,000 hours.
	Building door replacement	\$	12,000.00	\$	-	\$ 1,800.00	\$ 1,200.00	\$ 15,000.00	KV backside entrance & Side entrance. (solid & glass)
	Replace/remove classroom carpet, cove base, ceiling tile, and paint classrooms & hallway.	\$	177,368.00	\$	2,660.52	\$ 26,605.20	\$ 17,736.80	\$ 224,370.52	Dirks, Beasely, Hogue (library). Carpet can be removed for optional stain or natural cement floor finish.
	Instructional Programs	\$	50,000.00	\$	750.00	\$ 7,500.00	\$ 5,000.00	\$ 63,250.00	Workforce & Academic programs; welding lab - new bay door, cosmo lab - new student stations, program expansions, etc. This will fluctuate with program needs/requirements.
	Gymnasium	\$	50,000.00	\$	750.00	\$ 7,500.00	\$ 5,000.00		floor repairs/restriping (\$15,000), backboard lighting (\$1,200), scoreboard replacement (\$15K-\$30K), and electrical additions.
	Classroom & office signage	\$	10,000.00	\$	-	\$ 1,500.00	\$ 1,000.00	\$ 12,500.00	Wayfinders and updated signage to identify room numbers, buildings, etc.
	Roof repairs	\$	50,000.00	\$	750.00	\$ 7,500.00	\$ 5,000.00	\$ 63,250.00	BV Campus (apartments, dorms, gymnasium, Latcham, Day Care, etc.)
	Apartment kitchen remodel	\$	117,000.00	\$	1,755.00	\$ 17,550.00	\$ 11,700.00	\$ 148,005.00	Remodel and improve space in kitchen for apartments (20 units @ \$5,850 each)
	Building door entry card systems	\$	275,000.00	\$	4,125.00	\$ 41,250.00	\$ 27,500.00	\$ 347,875.00	Building entrances currently have key/lock system. This will replace all locking mechanisms with card/chip reader system that will improve all key management and govern building access.
	Electrical Engineering Assessment	\$	43,000.00	\$	645.00	\$ 6,450.00	\$ 4,300.00	\$ 54,395.00	Assessment will assist with master planning in identfying existing electrical systems condition, recommendations for improvements & costs for repairs/replacement/improvements.
12	Building Envelope Totals	\$	1,210,368.00	\$	15,575.52	\$ 181,555.20	\$ 121,036.80	\$ 1,510,935.52	
	EXTERIOR								
geo/cmt	Parking Lot repairs	\$	150,000.00	\$	-	\$ 22,500.00	\$ 15,000.00	\$ 187,500.00	Repairs & restriping college wide. BV: 8, KV:1, PL: 2, AL: 2
geo/cmt	Correct underground water drainage.	\$	25,000.00			\$ 3,750.00			AL Site parking lot drainage requires cleanout and proper drainage.
	Paint buildings	\$	50,000.00			\$ 7,500.00	\$ 5,000.00		All satelite campuses, apartments, dorms; bi-annually, fill in cracks, repair stucco, etc.
	Athletic Faciltiies - Soccer Field	\$	40,000.00			\$ 6,000.00	\$ 4,000.00	\$ 50,000.00	Soccer field fencing, wind screens, goal back-stop, signage, and seating.
	Zero-scape grounds areas	\$	20,000.00			\$ 3,000.00	\$ 2,000.00	\$ 25,000.00	Beeville Campus
	Level sidewalks	\$	25,000.00			\$ 3,750.00	\$ 2,500.00		May need to expand scope & estimate if deferred 2+ yrs., or revise design for master planning. BV & AL Site
	Repair/Paint handrails, campus-wide	\$	10,000.00			\$ 1,500.00	\$ 1,000.00		college wide
	Modify /Add seating	\$	35,000.00			\$ 5,250.00	\$ 3,500.00		Seating college-wide.
	Walking Trail	\$	50,000.00			\$ 7,500.00	\$ 5,000.00	\$ 62,500.00	Repairs on pavement, solar powered lighting, signage, etc.
	Campus irrigation system repair or replacement.	\$	20,000.00			\$ 3,000.00	\$ 2,000.00	\$ 25,000.00	Areas throughout campus require repairs/replacement due to shifting of terrain.
	Dormitory second story handrail repair or replacement	\$	25,000.00			\$ 3,750.00	\$ 2,500.00		These rails are rusted up and deteriorating. Requires repair or replacement.
	Exterior lighting	\$	25,000.00			\$ 3,750.00	\$ 2,500.00	\$ 31,250.00	Replace/repair lighting (BV, AL PL, Dorms,etc.)

		•								
										Assessment will assist with master planning in identifying existing architectural
	Architectural Engineering Analysis - Assessment	\$	30,000.00		\$	4,500.00	\$ 3,000.0	0   \$	37 500 00	condition, recommendations for improvements & costs for repairs/replacement/improvements.
13	Exterior Totals	\$	505.000.00	\$ -	\$	75,750.00	\$ 50.500.0	· •	•	
10	ZXOTO FOLIC	Ψ	000,000.00	<b>Y</b>	Ψ	70,700.00	Φ 00,000.0	<b>+</b>	001,200100	
	MECHANICAL									
	Repair pump foundations and replace leaking isolaiton valve	\$	20,000.00		\$	3,000.00	\$ 2,000.0	0 \$	25,000.00	Physical Plant; Beasley bldg;
	Replace 2 heat water pumps	\$	12,000.00		\$	1,800.00	\$ 1,200.0	0 \$	15,000.00	Physical Plant
asb	Replace duct system at AHU #14	\$	12,000.00		\$	1,800.00	\$ 1,200.0	0 \$	15,000.00	Jones Auditorium
asb	Replace 3-way heat control valve at AHU #12	\$	5,000.00		\$	750.00				Beasley Bldg; original equipment
asb	Replace AHU #9; heat coil and unit rusted out	\$	80,000.00		\$		\$ 8,000.0		100,000.00	Latcham Bldg; original equipment
asb	Replace AHU #10; heating coil leaking	\$	170,500.00		\$	25,575.00	\$ 17,050.0	0 \$	213,125.00	Beasley Bldg.; Original equipment nearing end of life cycle
asb	Replace AHU 1 & 2	\$	191,410.00		\$	28,711.50	\$ 19,141.0	0 \$	239,262.50	Marecek Gymnasium Basketball AHU's located above court, nearing life cyelce
asb	Replace AHU #3, unit only	\$	45,000.00		\$	6,750.00	\$ 4,500.0	0 \$	56,250.00	Marecek Gymnasium AHU's located in locker room/offices, nearing life cycle
asb	Replace AHU #4, unit only	\$	45,000.00		\$	6,750.00	\$ 4,500.0	0 \$	56,250.00	Marecek Gymnasium AHU's located in locker room/offices, nearing life cycle
asb	Replace AHU #2	\$	45,000.00		\$	6,750.00	\$ 4,500.0	0 \$	•	Student Union Bldg. (SUB) clogged coils, leaking drain pan, nearing life cycle.
asb	Replace chill/hot water underground piping, extend HVAC control software	\$	22,000.00		\$	3,300.00	\$ 2,200.0	0 \$	27,500.00	Benton Hall Dormitory underground system piping, nearing life cycle
asb	Repair obsolete electric heaters in ceiling	\$	15,000.00		\$	2,250.00	\$ 1,500.0	0 \$	•	J.Dougherty Dental Hygiene, not functioning, only used 3 months tops per year.
asb	Replace 3-way control valve actuator at AHU #5 & # 6	\$	1,200.00		\$	180.00	\$ 120.0	0 \$		Elam Bldg., nearing life cycle
	Replace HVAC units (19)	\$	311,017.00		\$	46,652.55	\$ 31,101.7	0 \$		Kingsville Site; units are 18-19 years or older. Nearing end/or past life cycle. (phasing in recommended). RTU's #5,6,22 rusted out. 4 units replaced 10/31/17 @\$33,983
	;	\$	80,000.00		\$	12,000.00	\$ 8,000.0	0 \$	100,000.00	Pleasanton Site; units are 15 years or older. Nearing end of life cycle.
asb	Replace HVAC units (4)	\$	80,000.00		\$	12,000.00	\$ 8,000.0	0 \$	100,000.00	F.Jostes Visual Arts; replace 20-30 year old units, past life cycle
asb	Replace main/gate valves, isolation valves & piping.	\$	400,000.00		\$	60,000.00	\$ 40,000.0	0 \$		Replace all tunnel original piping with new "aqutherm" insulated piping & valves. This can be completed in phases due to various section ratings and overall cost.
	Mechanical Engineering Analysis - Assessment	\$	40,000.00		\$	6,000.00	\$ 4,000.0	0 \$		This assessment will assist with master planning in identfying existing mechanical condition, recommendations for improvements & costs for repairs/replacement.
								_		
					\$	-	\$ -	\$		
18	Mechanical Totals	\$	1,575,127.00	\$ -	\$	236,269.05	\$ 157,512.7	0 \$	1,968,908.75	

15,575.52 \$

493,574.25 \$

329,049.50 \$

4,111,094.27

3,290,495.00 \$

Legend:							
APPA	APPA's Repairs & Rehabilitation Priority Levels						
geo/cmt	Geotechnical and/or Construction Materials Testing required						
asb	Project may require asbestos abatement						
	Related to Master Planning						

All Project Totals